

NEW ZEALAND GEOMECHANICS NEWS

JUNE 2003, ISSUE 65

CONTENTS

Chairman's Corner	2
Editorial	3
Editorial Policy	4
Report from the Secretary	4
International Society Reports	5
ISSMGE	5
ISRM	6
NZGS Branch Activities	9
Northern Area Student Prize Abstracts	12
Landsliding on the Paeroa Fault at Te Kopia	12
Spatial Variation in Auckland Residual Soil	13
Volcanic Debris Avalanche Deposits from Slope Failure of Tongariro and Kakaramea-Tihia Volcanoes, New Zealand	14
Geotechnical Hazards Affecting SH 31	15
Dynamic Response Calculations Using FLAC	16
Southern Area Student Prize Abstract	16
Design and Implementation of a Dense, Strong-motion Accelerograph Array for the Alpine Fault	16
Conference Reports	20
'Geotechnics on the Volcanic Edge' New Zealand Geological Society Symposium 2003	20
EUROCK 2002	22
GeoCart 2003	24
Standards, Law & Industry News	26
Guidelines for Classification and Description of Soils and Rocks – Comments on Draft	26
Are the Foundations on 'Good Ground'?	28
Book Review	31
Problem Solving in Soil Mechanics	31
Project News	32
Amelioration of Liquefaction Risk of the Tuaropaki Geothermal Power Station, Mokai, NZ	32
Estong Geogrids for Sub Grade Improvement Works	41
Functional Longevity for the Ages!	42
Special Interests	43
Total Geological History – A Model Approach to the Anticipation, Observation and Understanding of Site Conditions	43
Finite Elements in Soil Mechanics, Part VI	46
Technical Articles	51
The Window Sampler	51
Slope Stability Analysis – Variation or Validation?	53
Company Profiles	55
Member Profile	57
Foreign Correspondent – My Malaysian Roller Coaster Ride	61
The Bob Wallace Column	64
Events Diary	65
New Zealand Geotechnical Society Inc. Information	72
New Zealand Geotechnical Society Inc. Publications	75
Advertising Information	76

Cover photo: The Waihi subsidence of 13 December 2001, resulting from the collapse historical underground gold workings.
Photo Credit: Photo supplied by Keith Penny of Flinders, original source the *Waikato Times*.